

Garyg Miller/R6/USEPA/US

09/19/2007 10:46 AM

To "Eric Pastor" <eric.pastor@pbwllc.com>
cc lvoskov@tceq.state.tx.us
Subject Re: Gulfco Transformer Samples

Eric,

I have discussed the measured PCB levels with our TSCA folks and agree that no action is required under the PCB cleanup rules.

Regards,

Gary Miller
Remediation Project Manager
EPA Region 6 - Superfund (6SF-RA)
(214) 665-8318
miller.garyg@epa.gov

"Eric Pastor" <eric.pastor@pbwllc.com>

09/12/2007 01:23 PM

To Garyg Miller/R6/USEPA/US@EPA
cc
Subject

Hi Gary –

As I mentioned on the phone this morning, attached is the laboratory report for samples collected from the Gulfco transformer shed on Friday. TS-03 is a sample of mineral oil collected from one of the transformers. TS-04 is a sample of oil-soaked wood from the shed floor. TS-05 is a sample of oil-soaked cardboard that was observed on the shed floor. Based on the absence of PCBs in the oil sample and the trace PCB concentrations in the other two samples, we do not believe any action is required under the PCB spill cleanup rules or the standards applicable to PCB remediation waste (40 CFR Part 761). Please let me know if you have any questions, or would like additional information.

Thanks.

Eric Pastor
Pastor, Behling & Wheeler, LLC
2201 Double Creek Drive, Suite 4004
Round Rock, Texas 78664
(512) 671-3434



Transformer Shed Analytical Report.pdf